

Milling Machine Arbors Style B for 30-40-50 Spindle



Stock No.	Arbor No, Tapper No, Arbor Dia*Dia of Running Bushings*Length of Shoulder to Nut
1192-3101	model 31-B2 taper 30 1"x2", 1/2-13
1192-4001	model 40-7/8-B14-3 taper 40 7/8"x1-7/8"x14,5/8-11
1192-4002	model 40-7/8-B16-3 taper 40 7/8"x1-7/8"x16,5/8-11
1192-4101	model 41-B3 taper 40 1"x3", 5/8-11
1192-4102	model 41-B14-3 taper 40 1x1-7/8"x14,5/8-11
1192-4103	model 41-B20-3 taper 40 1x1-7/8"x20,5/8-11
1192-4104	model 41-1/4-B3 taper 40 1-1/4"x3", 5/8-11
1192-4105	model 41-1/4-B14-3 taper 40 1-1/4x1-7/8"x14,5/8-11
1192-4106	model 41-1/4-B20-3 taper 40 1-1/4x1-7/8"x20", 5/8-11
1192-4107	model 41-1/2-B10 taper 40 1-1/2x2-1/8"x10,5/8-11
1192-4108	model 41-1/2-B20-4 taper 40 1-1/2x2-1/8"x20,5/8-11
1192-5101	model 51-B3-1/2 taper 50 1x3-1/2, 1-8
1192-5102	model 31-B2 taper 30 1"x2", 1/2-13
1192-5103	model 51-B18-4 taper 50 1x2-1/8"x18,1-8
1192-5104	model 51-B24-4 taper 50 1x2-1/8"x24,1-8
1192-5105	model 51-1/4-B3-1/2 taper 50 1-1/4x3-1/2,1-8
1192-5106	model 51-1/4-B15-4 taper 50 1-1/4x2-1/8"x15,1-8
1192-5107	model 51-1/4-B18-4 taper 50 1-1/4x2-1/8"x18,1-8
1192-5108	model 51-1/4-B24-4 taper 50 1-1/4x2-1/8"x24,1-8
1192-5109	model 51-1/4-B30-4 taper 50 1-1/4x2-1/8"x30,1-8
1192-5110	model 51-1/2-B3-1/2 taper 50 1-1/2x3-1/2,1-8
1192-5111	model 51-1/2-B18-4 taper 50 1-1/2x2-1/8"x18,1-8
1192-5112	model 51-1/2-B24-5 taper 50 1-1/2x2-3/4"x24,1-8
1192-5113	model 51-1/2-B30-5 taper 50 1-1/2x2-3/4"x30,1-8
1192-5114	model 51-1/2-B36-5 taper 50 1-1/2x2-3/4"x36,1-8
1192-5201	model 52-B24-5 taper 50 2x2-3/4"x24,1-8
1192-5202	model 52-B30-5 taper 50 2x2-3/4"x30,1-8
1192-5203	model 52-B36-5 taper 50 2x2-3/4"x36,1-8

HITECH (Qingdao)
ENTERPRISES INC