

Milling Machine Arbors Style A for 30-40-50 Spindle



Style A with 23/32"*
1-3/4" pilots,
Machined from
high grade forging,
with standard key
ways and include
arbor spacers and
running bushings

Stock No.	Arbor No, Tapper No, Arbor Dia*Dia of Running Bushings*Length of Shoulder to Nut
1191-3001	Arbor No 30-7/8-A10-2 ,taper 30 ,7/8"x1-5/8"x10,1/2-13
1191-3101	Arbor No 31-A10-2 ,taper 30, 1"x1-5/8"x10,1/2-13
1191-3102	Arbor No 31-1/4-A10-2, taper 30, 1-1/4"x1-7/8"x10,1/2-13
1191-4001	Arbor No 40-7/8-A10,taper 40 ,7/8"x10,5/8-11
1191-4002	Arbor No 40-7/8-A16-3, taper 40, 7/8"x1-7/8"x16,5/8-11
1191-4101	Arbor No 41-A8 ,taper 40 ,1"x8,5/8-11
1191-4102	Arbor No 41-A10, taper 40 ,1"x10,5/8-11
1191-4103	Arbor No 41-A12 ,taper 40, 1"x12,5/8-11
1191-4104	Arbor No 41-A16-3, taper 40, 1"x1-7/8"x16,5/8-11
1191-4105	Arbor No 41-1/4--A8, taper 40, 1-1/4x8,5/8-11
1191-4106	Arbor No 41-1/4-A10, taper 40, 1-1/4"x10,5/8-11
1191-4107	Arbor No 41-1/4-A12, taper 40, 1-1/4"x12,5/8-11
1191-4108	Arbor No 41-1/4-A-16-3, taper 40, 1-1/4"x1-7/8"x16,5/8-11
1191-5001	Arbor No 50-7/8-A10, taper 50, 7/8x10,1-8
1191-5002	Arbor No 50-7/8-A18-4, taper 50, 7/8"x2-1/8"x18,1-8
1191-5101	Arbor No 51-A8, taper 50, 1"x8,1-8
1191-5102	Arbor No 51-A12, taper 50, 1"x2-1/8"x12,1-8
1191-5103	Arbor No 51-A18-4, taper 50, 1"x18,1-8
1191-5104	Arbor No 51-1/4-A8, taper 50, 1-1/4"x8,1-8
1191-5105	Arbor No 51-1/4-A12, taper 50, 1-1/4x12,1-8
1191-5106	Arbor No 51-1/4-A18-4, taper 50 ,1-1/4"x2-1/8"x18,1-8

HITECH (Qingdao)
ENTERPRISES INC